

Northeast Utilities Service Company P.O. Box 270 Hartford, CT 06141-0270 (860) 728-4532

March 17, 2014

Melanie Bachman, Acting Director Connecticut Siting Council Ten Franklin Square New Britain, CT 06051

Re:

Docket No. 435: Stamford Reliability Cable Project

Monthly Construction Progress Report

Dear Ms. Bachman:

Pursuant to Section 7.1 of the Development and Management Plan for the 115-kV underground transmission line and the South End Substation and Glenbrook Substation upgrades for the Stamford Reliability Cable Project. The Connecticut Light and Power Company ("CL&P") hereby provides a copy of the Monthly Construction Progress Report for February 2014.

Please contact me at 860-728-4532 with any questions that you or other Council members may have on this report.

Sincerely,

John Morissette

Project Manager - Transmission Siting

Enclosure

Docket 435 Stamford Reliability Cable Project CSC Monthly Construction Progress Report February 2014

UNDERGROUND TRANSMISSION LINE

No construction activities were performed on the underground transmission line. Construction will commence the week of March 17, 2014. While no construction activities were performed during February 2014, construction materials were delivered to the approved laydown areas in preparation for the start of construction.

SUBSTATIONS

Glenbrook Substation: Construction activities have commenced with the excavation for

foundations to support the installation the 115-kV intermediate

coupling capacitors for breaker protection, motor operated

disconnect switches and cable termination.

South End Substation: No construction activities were performed at the South End

Substation. Construction materials were delivered to the site in

preparation for construction start in March 2014.

MINOR DEVELOPMENT AND MANAGEMENT PLAN CHANGES

None.

ENVIRONMENTAL INSPECTIONS

On 2/26/14, CL&P's environmental contractor AECOM Technology Corporation conducted environmental inspections at Glenbrook Substation. AECOM observed that:

- Erosion and Sediment Controls are in place around catch basins and soil stockpile.
- The Erosion and Sediment Controls are installed correctly, and
- Overall inspection results are acceptable.