



BVH
integrated
services

Civil

**Study for Outside Air Quantity
25 Sigourney Street
Hartford, Connecticut**

Structural

Final Report

Mechanical

August 21, 2006

Electrical

Technology

**State of Connecticut
Department of Public Works
Project Number BI-2B-033 J**

BVH Project Number 21-06-056

Lighting Design

Commissioning

Special Services

50 Griffin Road South
Bloomfield, CT 06002

T: 860-286-9171

F: 860-242-0236

start@bvhis.com

www.bvhis.com

Table of Contents

1.	Introduction	2
2.	Review of Outside Air Quantity	3
3.	Outside Air Moisture	4
4.	Air Handling Unit Condensate Drainage	7
5.	Air Systems Replacement Scope of Work	8
5.1.	Air Handling Unit Replacement	8
5.2.	Replacement of VAV Boxes	9
5.3.	New Secondary Ductwork	9
6.	Cost Estimates.....	10
6.1.	Rebalancing of Outside Air Quantity	10
6.2.	Dehumidification Unit	10
6.3.	Air Handling Unit Replacement (per unit)	11
6.4.	VAV Box Replacement (per typical 30,000 square foot floor – floors 7-19).....	12
6.5.	Secondary Ductwork Replacement (per typical 30,000 square foot floor – floors 7-19)	13
7.	Conclusion and Recommendations	14

Appendix A – Wing’s Testing and Balancing Report dated June 21, 2006

Appendix B – Fan Data Related to Appendix A

Appendix C – Excerpts from Wing’s Testing and Balancing Report dated January 17, 2005

1. INTRODUCTION

BVH Integrated Services, Inc. was commissioned to investigate various aspects of the HVAC systems at 25 Sigourney Street in Hartford, Connecticut. The building is a 20 year old, 420,000 square foot high-rise office building that has been the subject of various indoor air quality investigations in the past. A report by Turner Building Science, LLC from December 2005 noted that the building HVAC systems were bringing in more outside air than necessary thus causing high humidity in the occupied space and ductwork during high humidity days. The purpose of this report is to determine if it is possible to reduce the amount of outside air delivered to the building while maintaining positive pressurization. A previous project corrected outside air infiltration and stack effect.

This study encompasses many aspects of the building's HVAC systems. The scope of the project is:

- Review existing outside air quantities delivered to building spaces and compare to outside air required based on current occupancy and assumed maximum capacity.
- Determine if it is possible to reduce outside air quantities in order to reduce moisture within ductwork and spaces while maintaining building pressurization.
- Provide scope and cost estimate for a dehumidification system for outside air if available outside air reduction is insufficient to reduce humidity levels.
- Assess condition of drain pans in existing air handling units throughout the building.
- Provide schematic cost estimate for replacement of existing air handling units, fiberglass ductwork, and VAV boxes including all costs such as ceiling removal and replacement.
- Provide a budget estimate for all recommended work.

The building is a 20 story mixed use office building. The building's mechanical systems are typical of speculative office buildings built in the same era. Each typical office floor is approximately 30,000 square feet with a north and south mechanical room on each typical floor. Each mechanical room has a variable volume air handling unit with hot and chilled water coils. Air is distributed to the floors to terminal VAV boxes with pneumatic controls. The air handling units and all head-end systems are controlled by direct digital controls (DDC).

Outside air is delivered to two shafts by two separate outside air fans at the penthouse level and distributed to each mechanical room. Outside air is mixed with return air within the mechanical room, which acts as a mixed air plenum. Each floor is equipped with an airflow station on the outside air duct which modulates a damper to maintain the specified outside air quantity on each floor. The airflow stations and dampers on the outside air deliver even ventilation throughout the building and equally pressurize each floor. A relief air shaft allows excess air on each floor (when more outside air is introduced on a floor than exhausted) to relieve, through gravity, to the roof level.

2. REVIEW OF OUTSIDE AIR QUANTITY

The December 2005 report by Turner Building Science, LLC noted that existing outside air quantities exceed ASHRAE recommendations for minimum outside air by "2-3 times". Current building code and the building code at the time of the controls upgrade project dictates the amount of outside air required per occupant and dictates the number of occupants that must be used for the design.

Per code, design occupancy for each 30,000 (approximate) square foot floor plate of office is seven occupants per 1,000 square feet, which equates to 210 occupants per typical floor. The code outside air requirement is 20 cfm per person. This equates to 4,200 cfm per floor, or 2,100 cfm per air handling unit. The current outside air setting on each typical air handling unit is 2,200 cfm. To calculate outside air for the entire building, 420,000 square feet equates to an occupancy of 2,940 people. At 20 cfm/person, 58,800 cfm is required for minimum ventilation in the building.

The two existing outside air fans were designed to deliver 49,000 cfm each for a total of 98,000 cfm. The original design included provisions for air-side economizer operation; the minimum outside air delivery was 61,300 cfm total for both fans and controls allowed the fans to increase in speed to deliver 98,000 cfm in economizer. According to recent testing by Wing's Testing and Balancing (July 15 2004), the outside air fans deliver 60,713 cfm at minimum outside air and 81,480 cfm at economizer operation (maximum air delivery).

The existing ventilation meets current code requirements. Each floor receives about 20 percent outside air at peak design conditions which is typical of office buildings and exceeds minimum requirements by 3.3 percent, which is within standard balancing tolerances.

According to operations staff, the actual peak occupancy is not expected to exceed 1,500 people. Using this occupancy as a basis for design, outside air could, theoretically, be reduced to 30,000 cfm for the entire building. Any reduction in outside air quantities should be reviewed with the authority having jurisdiction; adequate proof of occupancy rates well below code requirements will be required in order to reduce outside air quantities to this level.

In addition to providing ventilation for building occupants, the outside air also pressurizes each floor to prevent potential moisture infiltration through the building envelope. Pressurization controls on each floor modulate the relief air damper on the floor in order to maintain the pressurization setpoint. Any reduction in outside air will require a reduction in the pressurization setpoint.

The current exhaust air from the building is approximately 26,300 cfm, compared to an outside air delivery of approximately 60,713 cfm. The excess air for pressurization is 34,413 cfm. Theoretically, the outside air quantity could be reduced to 30,000 cfm without producing a negative pressure and still provide enough ventilation for the assumed peak occupancy of 1,500 people. Due to the height of the building, however, equalizing the outside air and the exhaust air would likely produce a positive pressure on upper floors and a negative pressure on lower floors. Each typical floor has about 4,400 cfm of outside air at minimum conditions and 1,200 cfm exhaust. The

positive pressurization for each floor is about 3,200 cfm (note, this is a general statement and varies from floor to floor), which is removed through the relief air shaft.

The existing pressurization controls are set to maintain 0.20 inches of water differential pressure between the interior space and atmospheric pressure. The controls modulate the relief dampers on each floor to maintain the setpoint on each floor. Observations of the existing controls showed that the measured floor pressurization varied from floor to floor but, on average, was sufficiently positive. The floor static setpoint is high and can be reduced to 0.10 inches, a number that is used for healthcare and clean room pressurization applications. Reducing this number may help to reduce the pressure on the floors that are pressurized above setpoint and increase the pressure on floors where pressure is below the setpoint.

A motorized damper at the top of the relief shaft controls the total building pressurization. The control system is set up to utilize an average of all of the floor pressures. The total building static pressure setpoint at the controls was set at 0.05 inches and was observed to be measuring between 0.03 and 0.10 inches. The setpoint for this control should match the setpoint for the individual floor controls. It was observed that the relief damper modulated rapidly and appeared to need some fine tuning.

Utilizing the current relationship of pressure and flow rate differential, it may be possible to reduce outside air flow and maintain 0.10 inches positive pressure on each floor. Based on current relationships, the total outside air quantity could be reduced by about 30 percent. This would reduce the differential cfm between outside air and exhaust air from 34,413 cfm to 24,100 cfm, reducing total outside air at minimum conditions to 50,400 cfm. We would not recommend reducing airflow any lower than this number. This reduction in airflow should be done proportionally at each floor and should be performed by a commissioning agent, a certified testing and balancing agency, and a control technician. The reduction should be done by trial and error to assure that positive pressurization is maintained. If pressurization cannot be maintained at the minimum airflow prescribed in this report, then the airflow should be increased until the pressurization is maintained. The building Owner should approach the authority having jurisdiction with population data to assure that a reduction in outside air below code requirements is acceptable.

3. OUTSIDE AIR MOISTURE

The Turner Building Science Report noted that the existing HVAC system brings in "large quantities of raw, unconditioned outside air," which may be responsible for mold growth in the air handling units and in the distribution ductwork. As discussed in the previous section, the amount of outside air is typical of an office building and meets current code requirements. The physical amount of outside air delivered to the building does not create any abnormal moisture issues above and beyond typical HVAC systems for this building type. The delivery method could create moisture infiltration through the outside air shaft walls and, potentially, higher than normal moisture levels in the mechanical room. If the systems are operating as designed, the mechanical room will be under a negative pressure which will prevent any moisture infiltration to the occupied space and if the outside air shafts are properly sealed, there is no route for moisture to pass between the shaft and the occupied space. The outside air shafts are reported to be in good condition.

The outside air is mixed with return air in the mechanical room (which acts as a mixing plenum) and drawn into the air handling unit. Each air handling unit is equipped with a chilled water cooling coil which provides moisture removal from the mixed air stream.

As described in the previous section, the air systems have a limited economizer which allows additional outside air into the mechanical room plenum. The economizer controls are based on enthalpy, which takes into account both moisture and temperature. The controls will not allow the system, for example, to go into economizer operation on a very humid day with a moderate outside air temperature in the economizer temperature range.

The 0.4 percent design dehumidification day in Hartford, per ASHRAE climatic data, is 81 deg. F dry bulb/75 deg. F wet bulb (approximately 76% RH). This condition would be the basis of design for a dehumidification system; it's considered worst case for moisture (on average, only 0.4% of the year would have more moisture in the outside air than this). During these conditions, the outside air fans would be delivering minimum outside air.

To take, for example, the mechanical room with the highest amount of minimum outside air after balancing was performed on July 15, 2004 by Wing's Testing and Balancing, was in mechanical room 14N. The minimum outside air to this unit was balanced at 2,333 cfm. The design airflow for this unit is 14,500 cfm. It is reasonable to assume that the zone load would not be at full load under these conditions – taking an 80 percent diversity factor, the total supply air would be 11,600 cfm. The outside air percentage is around 20 percent at this condition. Assuming a return air condition of 78 deg. F, 50% RH, the mixed air condition would be 79 deg. F dry bulb/67.5 deg. F wet bulb, which has slightly more moisture than the original coil design entering air condition of 79/66. The cooling coil would still remove moisture from the air in this condition, but the relative humidity may creep up slowly in the space if the coil was unable to remove all the moisture in the air. Relative humidity sensors could be installed on different floors to monitor humidity with the existing system operation to see if this is the case.

The TBS report also noted that moisture levels in the building would promote mold growth if the outside air had a high relative humidity and the cooling coils were not in operation. Due to the low amounts of outside air, there are no conditions where the humidity ratio of the outside air is greater than the humidity ratio of the inside air where the cooling coil wouldn't be active. It is also unlikely that the surface temperature inside the air handling unit would fall below the dewpoint of the discharge air and cause condensation on the inside surfaces of the unit, as long as the outside air is off during unoccupied periods (which is the current control scheme).

This may have been a problem in the past before the recent controls upgrade. Condensation could occur regularly during the summer on the outside of the casing due to warm mixed air in the mechanical room in areas where the casing



Figure 1 - Air handling unit with failing insulation

insulation within the air handling unit had worn away or fallen off. The existing internal insulation on all units is being replaced and should be complete at the time of the issue of this report.

A likely cause of moisture penetration on the former internal casing of the air handling unit and on fiberglass liner in the ductwork just downstream of the fan is moisture carryover due to a high velocity at the cooling coil. As the moisture condenses on the cooling coil, it drips down the coil and collects in the drain pan. As the velocity increases at the coil, the likelihood that the drops of condensation will be pulled into the airstream increases. Standard design typically limits the face velocity at the coil to 500-550 feet per minute. According to the most recent test report (July 14, 2005 – Wing’s Testing and Balancing), the velocity at design conditions was 760 feet per minute on the typical floors. This velocity is not unusual with limited mechanical space, which is the case with this building.

Moisture carryover can be reduced with larger air handling units (or larger cooling coil face area), by installing moisture eliminators downstream of the cooling coil, or dehumidifying the outside air. The first two options require new air handling equipment in limited mechanical space. The dehumidification unit would have to be sized for economizer operation at 100,000 cfm (to match the original design and maximize the energy-saving capabilities of the system, which is limited by the existing outside air shaft sizes). A dehumidification unit would also reduce the possibility of moisture migration through the walls of the outside air shafts.

The existing mechanical rooms that house the outside air fans do not have enough space to accommodate a dehumidification unit, so a single unit would have to be placed on the roof of the penthouse and ducted over to the two existing shafts. A new pair of chilled and hot water risers originating from the service entrance of the thermal utilities in the basement would be required to serve the dehumidification unit. Significant structural modifications would likely be required in order support the unit on the roof; the scope of this work is unknown at this time.

Placement of the dehumidification unit would be crucial due to the proximity of the cooling tower discharge, which would be at the same elevation as the new intake location on the roof of the penthouse. If this option were to be pursued, a wind study using tracer gases should be commissioned to assure that the cooling tower plume will not be entrained into the outside air intake. It should be noted that the current outside air intake locations are sufficiently separated from the cooling tower plume and are located below the cooling tower discharge.

As an option, a heat recovery wheel could be added to the system to recapture heat from the toilet exhaust, as suggested in the TBS report. This would require a new toilet exhaust fan and additional ductwork from the fan to the dehumidification unit. Pricing for dehumidification options can be found in Section 6.

Another way to minimize moisture in the space is to have an unoccupied set-up temperature setpoint that will allow the individual air handling units to cycle on without any outside air to cool the space so that space temperatures and humidity levels don’t become excessive over long periods of unoccupied periods. A standard set-up setpoint is 85 degrees. Control can also be set on relative humidity levels; the existing control system is not equipped with relative humidity sensors on each floor.

4. AIR HANDLING UNIT CONDENSATE DRAINAGE

The existing air handling units utilize the floor of the fan section to drain condensate. With the exception of the 19th floor unit (in the penthouse mechanical room), each unit was only drained from one side. The opposite sides of the units were inaccessible and the drain connection was capped. It was not possible to see if all of the bases were sloped to one side, but the floors of the units were not uniformly flat due to their age; the surfaces lent themselves to condensate ponding.

During the time of our survey, the units were in the process of being cleaned and re-insulated and the drain section was being coated with an anti-microbial coating. This process will be complete for all air handling units by the time the final report is submitted. Finished units were clean and in better condition than units that had not been serviced. Internal fiberglass insulation was loose on the unfinished units and the floors of the units in the fan section were corroded and in poor condition in most cases.

According to the manufacturer of the existing units (Trane), the casing is structural and there is no way to cut a new drain pan in under the existing cooling coil. It may be possible to fabricate a stainless steel drain pan and slide it under the existing coil (there is about 2 inches of clearance between the bottom of the coil and the floor of the unit), but access is limited and proper attachment would be difficult. In addition, there is not enough vertical clearance to properly pitch the drain pan to one side of the unit.

The condensate traps appeared to be properly sized throughout. Condensate discharge piping on many units needed to be adequately secured to the floor to maintain pitch.




Figure 2 - Existing drain pan before refurbishment



Figure 3 - Condensate drain piping pitched away from drain



Figure 4 - Refurbished air handling unit floor

The new coating appears to have improved the condition of the floor, but proper pitch inside the unit cannot be verified or corrected because of the drainage arrangement. Since the unit is equipped with two drain connections and only one is connected on most units, it is possible that the floor is not draining properly in all cases. As part of preventative maintenance, pitch of discharge piping should be examined periodically and corrected, if necessary. Additionally, the fan section bases should be examined periodically during high humidity days to assure proper drainage. The units are nearing the end of their expected useful life and should be considered for replacement with units equipped with stainless steel IAQ drain pans.

5. AIR SYSTEMS REPLACEMENT SCOPE OF WORK

The scope of work described by operations staff for replacement of existing HVAC systems includes the replacement of existing air handling units, replacement of existing VAV boxes, and replacement of existing secondary ductwork (fiberglass duct downstream of VAV boxes). The scope for these improvements will be broken into three components so that work can be prioritized.

5.1. Air Handling Unit Replacement

Scope of work (typical for each mechanical room):

- Remove existing air handling unit, supply ductwork within the mechanical room, existing cooling and heating coil connections, supports, electrical connections, controls, and all associated accessories.
- Provide a new air handling unit sized for approximately 500 feet per minute at design airflow with chilled water cooling coil and hot water heating coil.
- Unit shall be equipped with a stainless steel IAQ drain pan with single or double-sided connections depending on accessibility.
- Supply fan motor shall be premium efficient and meet or exceed the more stringent of code requirements or Northeast Utilities' Energy Conscious Construction program.
- Unit shall be equipped with 85% efficient filters with 30% pre-filters.
- Reuse existing control valves and sensing devices.
- Provide new supply ductwork within mechanical room with acoustic lining that meets UL and ASTM standards for erosion, moisture, fungi and bacteria resistance.
- Reuse existing variable frequency drives.
- Provide new condensate drain piping and properly-sized trap to existing floor drain.

5.2. Replacement of VAV Boxes

Typical scope of work:

- Remove existing VAV boxes and associated hangers and supports.
- Remove existing hot water piping to boxes with hot water reheat coils – cap piping and save for reuse.
- Remove existing pneumatic controls back to source.
- Provide new supply ductwork within mechanical room with acoustic lining that meets UL and ASTM standards for erosion, moisture, fungi and bacteria resistance.
- Reconnect hot water to boxes with hot water coils; provide new DDC control valve and all new trim.
- Replace existing zone thermostat with new DDC temperature sensor.
- Provide box with DDC controls tied into existing building management system.
- Provide new power to fan-powered VAV boxes.

5.3. New Secondary Ductwork

Typical scope of work:

- Remove all existing secondary ductwork between VAV boxes and diffusers.
- Provide all new galvanized steel ductwork between VAV boxes and diffusers.
- Provide all new flexible ductwork for runouts to diffusers in accessible ceiling areas (maximum flexible duct run of 6 feet).
- Provide new volume dampers at all duct takeoffs.
- Line first 10 feet of ductwork downstream of VAV boxes with acoustic lining that meets UL and ASTM standards for erosion, moisture, fungi and bacteria resistance.
- Insulate all supply ductwork with 1.5 inches fiberglass insulation with vapor barrier.
- Remove existing ceilings and install new ceilings.
- Remove existing light fixtures and ceiling devices and save for reuse.

6. COST ESTIMATES

The following is an assessment of the estimated costs associated with the recommendations made in the previous sections. Note that costs do not include any provisions for escalation and are conceptual level cost estimates for budgetary purposes only. All construction work is assumed to be on premium time. Estimates include (where noted) 35 percent for soft costs and do not include costs associated with the impact on operations or costs for cleaning upon completion.

6.1. Rebalancing of Outside Air Quantity, Commissioning, and ATC Programming Adjustments

<i>Item</i>	<i>Estimated Cost</i>
Commissioning, Testing, and Balancing	\$24,000
Control Technician	\$ 4,000
Total	\$28,000

6.2. Dehumidification Unit

Base Unit (No Heat Recovery):

<i>Item</i>	<i>Estimated Cost</i>
Dehumidification Unit	\$250,000
Rigging and Installation	\$180,000
New Chilled and Hot Water Risers (assuming straight path up through building)	\$125,000
Roof-Mounted Ductwork (insulated)	\$ 50,000
Demolition	\$ 25,000
Controls	\$ 20,000
Testing and Balancing	\$ 4,000
Electrical	\$ 20,000
Structural Modifications	\$125,000
General Conditions, Contractor OH&P	\$160,000
Soft Costs	\$336,000
Total	\$1,295,000

Alternate Unit (With Heat Recovery):

<i>Item</i>	<i>Estimated Cost</i>
Base Cost	\$1,295,000
Heat Recovery Section	\$ 250,000
Additional Ductwork, Exhaust Fan	\$ 35,000
Additional Balancing	\$ 1,500
Additional Controls	\$ 15,000
Additional Electrical	\$ 8,000
Additional General Conditions, Contractor OH&P	\$ 62,000
Additional Soft Costs	\$ 130,000
Total	\$1,796,500

6.3. Air Handling Unit Replacement

<i>Item</i>	<i>Estimated Cost (Each Unit, Floors 6S, 7-19)</i>	<i>Estimated Cost (Each Unit, Lobby and 6N)</i>	<i>Estimated Cost (Floor 20)</i>
Air Handling Unit	\$ 25,000	\$ 19,000	\$ 12,000
Installation and Rigging	\$ 15,000	\$ 15,000	\$ 20,000
Piping and Insulation	\$ 7,000	\$ 7,000	\$ 7,000
Ductwork and Insulation	\$ 10,000	\$ 9,000	\$ 7,500
Controls	\$ 8,000	\$ 8,000	\$ 8,000
Demolition	\$ 9,000	\$ 9,000	\$ 9,000
Testing and Balancing	\$ 2,000	\$ 2,000	\$ 2,000
Electrical Power	\$ 6,000	\$ 6,000	\$ 6,000
Fire Alarm Modifications	\$ 6,000	\$ 6,000	\$ 6,000
General Conditions, Contractor OH&P	\$ 18,000	\$ 16,000	\$ 15,500
Soft Costs	\$ 37,000	\$ 34,000	\$ 32,500
Total (each unit)	\$143,000	\$131,000	\$125,500
Total (all 29 units)	\$3,831,500		



6.4. VAV Box Replacement

<i>Item</i>	<i>Estimated Cost (Each Floor, Floors 7-19)</i>	<i>Estimated Cost (Lobby and 6th Floor)</i>	<i>Estimated Cost (Floor 20)</i>
VAV Boxes (assuming 800 SF/zone)	\$110,000	\$115,000	\$ 20,000
Piping Reconnections and Insulation	\$ 25,000	\$ 27,000	\$ 5,000
Ductwork Reconnections and Transitions	\$ 25,000	\$ 27,000	\$ 5,000
Controls	\$115,000	\$120,000	\$ 22,000
Testing and Balancing	\$ 8,000	\$ 9,000	\$ 1,500
Demolition	\$ 15,000	\$ 16,000	\$ 2,000
Electrical	\$ 20,000	\$ 25,000	\$ 5,000
Ceiling Removal and Installation of New	\$ 30,000	\$ 40,000	\$ 5,000
General Conditions, Contractor OH&P	\$ 70,000	\$ 76,000	\$ 13,100
Soft Costs	\$146,000	\$159,000	\$ 27,500
Total (per floor)	\$564,000	\$614,000	\$106,100
Total (entire building)	\$7,488,000		

6.5. Secondary Ductwork Replacement

<i>Item</i>	<i>Estimated Cost (Each Floor, Floors 7-19)</i>	<i>Estimated Cost (Lobby and 6th Floor)</i>	<i>Estimated Cost (Floor 20)</i>
Demolition	\$ 35,000	\$ 40,000	\$ 8,000
New Sheet Metal Ductwork	\$125,000	\$135,000	\$ 40,000
Duct Accessories	\$ 45,000	\$ 50,000	\$ 8,000
Duct Insulation and Lining	\$ 68,000	\$ 74,000	\$ 15,000
Testing and Balancing	\$ 15,000	\$ 18,000	\$ 3,000
Electrical Associated with Ceiling Work	\$ 75,000	\$ 80,000	\$ 15,000
Ceiling Removal and Installation of New	\$180,000	\$210,000	\$ 30,000
Allowance for Conflicts with Existing Utilities and Systems	\$ 15,000	\$ 20,000	\$ 5,000
General Conditions, Contractor OH&P	\$112,000	\$125,000	\$ 25,000
Soft Costs	\$235,000	\$263,000	\$ 52,000
Total (per floor)	\$905,000	\$1,015,000	\$201,000
Total (entire building)	\$12,076,000		

7. CONCLUSION AND RECOMMENDATIONS

Based on the findings of this report, we recommend the following:

- Balance existing outside air quantity down to no lower than 50,400 cfm total for both outside air fans. This reduction in airflow should be done proportionally at each floor and should be performed by a commissioning agent, a certified testing and balancing agency, and a control technician. The building Owner should approach the authority having jurisdiction with population data to assure that a reduction in outside air below code requirements is acceptable. Once airflow is reduced, pressure readings should be taken to assure that all floors are positively pressurized. Where floors are not positively pressurized, minimum outside air should be increased until the floor is positive. Pressurization setpoints should be changed to 0.10 inches. Existing CO2 ventilation controls and economizer controls shall continue to operate under the current control scheme. As part of the scope of this work, the following additional items should be investigated and, if necessary, corrected:
 - ⇒ Confirm control sequences for pressurization and outside air match specified control sequences
 - ⇒ Pressurization control should be able to operate on high pressure, low pressure, or average pressure at the user interface
 - ⇒ Review existing control programming loop for building relief damper and tune to smooth operation and alleviate swings in building pressure
 - ⇒ Pneumatic relief dampers on each floor should be investigated to assure that they close tightly when controls command dampers closed
- Consider installation of new dehumidification unit for outside air delivery. Perform life cycle cost analysis to determine if heat recovery is a viable option. Perform modeling to assure that cooling tower plume is not drawn into new outside air intake location.
- Existing air handling units are approaching the end of their expected useful lives and should be replaced within 5 to 10 years. When units are replaced, they should be replaced with units that have a greater face area that will minimize the carryover of condensation from the cooling coil and are equipped with IAQ drain pans. If properly designed and installed, the new units will eliminate condensation issues that would otherwise be mitigated by the installation of a dehumidification unit. In lieu of installing the dehumidification unit on the roof, we recommend accelerating the replacement of the existing air handling units as this is a more cost effective way to deal with any moisture issues in the occupied space. The only part of the system that would be exposed to direct outside air would be the outside air intake shafts. The shafts are reported to be in good condition by building management. Ideally, units should be replaced on unoccupied floors to minimize cost and disruption. The existing duct system is a loop system that allows for one unit to feed a whole floor when the other is shut down. This arrangement provides about 50-60% of the total available capacity to the floor. This amount of capacity should be sufficient to provide adequate (though not perfect) conditioning during the winter and some of the shoulder seasons. Units should not be replaced on occupied floors

during the summer; one unit will not have enough capacity to keep the occupants comfortable on most summer days. Installation on an occupied floor would take about 2-3 weeks. If the floor was unoccupied, the work could be done in about 7-10 days since both units could be replaced at the same time.

- Initiate a preventative maintenance program to assure that all existing condensate drain piping is properly pitched and draining on existing units until new units are installed.
- Begin phased replacement of existing VAV boxes and secondary fiberglass ductwork. If feasible, VAV boxes and secondary ductwork should be replaced at the same time to minimize disruption and reduce overall cost. If not done at the same time, the VAV boxes should be replaced first, then secondary ductwork should be replaced. Ideally, the secondary ductwork should be replaced when floors are unoccupied to reduce cost and disruption. If work is done while floors are occupied, ceilings will have to be removed and reinstalled each night or weekend and much of the contractor's productive time will be spent on preparation before and reinstallation and cleaning after. Replacement of VAV boxes and secondary ductwork should be phased after the installation of new air handling units.

W:/2006/2106056/docs/21-06-056-R-JSC-2006-06-26-Final 25 Sigourney St Air Quantity Study.doc



BVH
integrated
services

Alternate Unit (With Heat Recovery):

<i>Item</i>	<i>Estimated Cost</i>
Base Cost	\$1,295,000
Heat Recovery Section	\$ 250,000
Additional Ductwork, Exhaust Fan	\$ 35,000
Additional Balancing	\$ 1,500
Additional Controls	\$ 15,000
Additional Electrical	\$ 8,000
Additional General Conditions, Contractor OH&P	\$ 62,000
Additional Soft Costs	\$ 130,000
Total	\$1,796,500

6.3. Air Handling Unit Replacement

<i>Item</i>	<i>Estimated Cost (Each Unit, Floors 6S, 7-19)</i>	<i>Estimated Cost (Each Unit, Lobby and 6N)</i>	<i>Estimated Cost (Floor 20)</i>
Air Handling Unit	\$ 25,000	\$ 19,000	\$ 12,000
Installation and Rigging	\$ 15,000	\$ 15,000	\$ 20,000
Piping and Insulation	\$ 7,000	\$ 7,000	\$ 7,000
Ductwork and Insulation	\$ 10,000	\$ 9,000	\$ 7,500
Controls	\$ 8,000	\$ 8,000	\$ 8,000
Demolition	\$ 9,000	\$ 9,000	\$ 9,000
Testing and Balancing	\$ 2,000	\$ 2,000	\$ 2,000
Electrical Power	\$ 6,000	\$ 6,000	\$ 6,000
Fire Alarm Modifications	\$ 6,000	\$ 6,000	\$ 6,000
General Conditions, Contractor OH&P	\$ 18,000	\$ 16,000	\$ 15,500
Soft Costs	\$ 37,000	\$ 34,000	\$ 32,500
Total (each unit)	\$143,000	\$131,000	\$125,500
Total (all 29 units)	\$3,831,500		

35%

8%

Backup # 4



6.4. VAV Box Replacement

<i>Item</i>	<i>Estimated Cost (Each Floor, Floors 7-19)</i>	<i>Estimated Cost (Lobby and 6th Floor)</i>	<i>Estimated Cost (Floor 20)</i>
VAV Boxes (assuming 800 SF/zone)	\$ 110,000	\$ 115,000	\$ 20,000
Piping Reconnections and Insulation	\$ 25,000	\$ 27,000	\$ 5,000
Ductwork Reconnections and Transitions	\$ 25,000	\$ 27,000	\$ 5,000
Controls	\$ 115,000	\$ 120,000	\$ 22,000
Testing and Balancing	\$ 8,000	\$ 9,000	\$ 1,500
Demolition	\$ 15,000	\$ 16,000	\$ 2,000
Electrical	\$ 20,000	\$ 25,000	\$ 5,000
Ceiling Removal and Installation of New	\$ 30,000	\$ 40,000	\$ 5,000
General Conditions, Contractor OH&P	\$ 70,000	\$ 76,000	\$ 13,100
Soft Costs	\$ 146,000	\$ 159,000	\$ 27,500
Total (per floor)	\$564,000	\$614,000	\$106,100
Total (entire building)	\$7,488,000		

10.0

BACK up to # 5



6.5. Secondary Ductwork Replacement

<i>Item</i>	<i>Estimated Cost (Each Floor, Floors 7-19)</i>	<i>Estimated Cost (Lobby and 6th Floor)</i>	<i>Estimated Cost (Floor 20)</i>
Demolition	\$ 35,000	\$ 40,000	\$ 8,000
New Sheet Metal Ductwork	\$125,000	\$135,000	\$ 40,000
Duct Accessories	\$ 45,000	\$ 50,000	\$ 8,000
Duct Insulation and Lining	\$ 68,000	\$ 74,000	\$ 15,000
Testing and Balancing	\$ 15,000	\$ 18,000	\$ 3,000
Electrical Associated with Ceiling Work	\$ 75,000	\$ 80,000	\$ 15,000
Ceiling Removal and Installation of New	\$180,000	\$210,000	\$ 30,000
Allowance for Conflicts with Existing Utilities and Systems	\$ 15,000	\$ 20,000	\$ 5,000
General Conditions, Contractor OH&P	\$112,000	\$125,000	\$ 25,000
Soft Costs	\$235,000	\$263,000	\$ 52,000
Total (per floor)	\$905,000	\$1,015,000	\$201,000
Total (entire building)	\$12,076,000		

Nakos, George

From: Moore, Doug
Sent: Monday, January 07, 2013 9:47 AM
To: Nakos, George
Subject: FW: Turner building sciences report long range recommendations & estimates with back up
Attachments: Turner report recommended long range building improvements.doc; back up for turners report recs.pdf

From: Brown, Jacquelyn
Sent: Monday, January 07, 2013 9:39 AM
To: Moore, Doug
Subject: FW: Turner building sciences report long range recommendations & estimates with back up

From: Brown, Jacquelyn
Sent: Friday, September 23, 2011 10:54 AM
To: Moore, Doug
Cc: Morrin, Laureen P.; Bantz, Marilyn
Subject: Turner building sciences report long range recommendations & estimates with back up

Turner report recommended long range building improvements

Note: Turner report noted that ALL recommendations eventually be addressed in order to provide a consistently healthy & comfortable & manageable indoor environment:

1. Turner report recommendation: to install dehumidification to help control humidity levels in the building: JHV
BVH consultant study identified it would be more effective to replace existing air handling unit equipment with newly designed system that could better control humidity because existing equipment was at the end of their useful life.
 - 2006 study estimate for AHU replacement on all floors: ~3.9 million adjusting for current costs, additional design and construction cost to handle working in an occupied space: ~5.0 million (see back up attached).
2. Turner recommendations to evaluate/ install a drainage plane between exterior façade and interior for more consistent control water infiltration in the future:
 - Benassi architects study in 2006 provided options and estimates for drainage plane work estimated between 7.3 and 7.8 million in 2006 – estimated current cost including costs associated with construction limitations due to working in an occupied building (like barrier installation or providing swing space or afterhours work etc): 10.0 million (see back up attached)
3. Turner recommendation to remove/ redesign of exterior balconies:
 - Benassi study 2006 estimate for design/enclosure of balconies 2.5 million. Estimated current cost including costs associated with construction limitations due to working in an occupied building: 5.0 million (see back up attached)
4. Turner recommendation to replace existing variable air volume controls with digital controls: VHV
 - 2006 BVH study estimate: 7.5 million. Current estimated costs including cost associated with construction limitations due to working in an occupied building: 10.0 million (see back up attached)
5. Turner recommendation to replace old duct board/fiberglass lined ductwork:
 - BVH 2006 study estimate to replace secondary ductwork 12.1 million. Current estimate including costs associated with construction limitations due to working in an occupied building: 15.0 million (see back up attached)
6. LOWER PRIORITY Turner recommendation to Install perimeter radiation and consider eliminating 2/3rds of exterior glazing (ie to better control temps along perimeter):
 - Estimate: 3.0 million
7. LOWER PRIORITY Turner recommendation for 100 % exhaust of kitchenette area on each floor to improve indoor air quality (by eliminating odors)
 - Estimate in excess of 2.0 million

Turner report recommended long range building improvements

Note: Turner report noted that ALL recommendations eventually be addressed in order to provide a consistently healthy & comfortable & manageable indoor environment:

1. Turner report recommendation: to install dehumidification to help control humidity levels in the building: JH ✓
BVH consultant study identified it would be more effective to replace existing air handling unit equipment with newly designed system that could better control humidity because existing equipment was at the end of their useful life.
 - 2006 study estimate for AHU replacement on all floors: ~3.9 million adjusting for current costs, additional design and construction cost to handle working in an occupied space: ~5.0 million (see back up attached).
2. Turner recommendations to evaluate/ install a drainage plane between exterior façade and interior for more consistent control water infiltration in the future:
 - Benassi architects study in 2006 provided options and estimates for drainage plane work estimated between 7.3 and 7.8 million in 2006 – estimated current cost including costs associated with construction limitations due to working in an occupied building (like barrier installation or providing swing space or afterhours work etc): 10.0 million (see back up attached)
3. Turner recommendation to remove/ redesign of exterior balconies:
 - Benassi study 2006 estimate for design/enclosure of balconies 2.5 million. Estimated current cost including costs associated with construction limitations due to working in an occupied building: 5.0 million (see back up attached)
4. Turner recommendation to replace existing variable air volume controls with digital controls: VX ✓
 - 2006 BVH study estimate: 7.5 million. Current estimated costs including cost associated with construction limitations due to working in an occupied building: 10.0 million (see back up attached)
5. Turner recommendation to replace old duct board/fiberglass lined ductwork:
 - BVH 2006 study estimate to replace secondary ductwork 12.1 million. Current estimate including costs associated with construction limitations due to working in an occupied building: 15.0 million (see back up attached)
6. LOWER PRIORITY Turner recommendation to Install perimeter radiation and consider eliminating 2/3rds of exterior glazing (ie to better control temps along perimeter):
 - Estimate: 3.0 million
7. LOWER PRIORITY Turner recommendation for 100 % exhaust of kitchenette area on each floor to improve indoor air quality (by eliminating odors)
 - Estimate in excess of 2.0 million

Back up for Rec. estimate
 # 2

Martin A. Benassi AIA		COST ESTIMATE - Appendix C				Design Phase
Architect		DPW #BI-2B-033-I				
Drainage Plane Study - 25 Sigourney Street		Date: July 21, 2006				Page 1 of 5
DIV.	PRINCIPAL TRADE ITEM AND ITEM DESCRIPTION	UNIT	QTY	UNIT PRICE	ITEM PRICE	SELECTED ITEM COST
	GENERAL					
	bonding, insurance, general administrative	unit	1	\$150,000.00	\$150,000.00	
	scaffolding, swing staging rental and equip.	mo	4	\$6,000.00	\$24,000.00	
	site foreman, supervision	mo	4	\$11,000.00	\$44,000.00	
						\$218,000.00
	OPTION A - add rainscreen system					
	add alum rainscreen system with all related flashing	sf	107,100	\$45.00	\$4,819,500.00	
	additional rigid insulation 1 inch thick	sf	107,100	\$0.80	\$85,680.00	
						\$4,905,180.00
	SUB-TOTAL					\$5,123,180.00
	city cost index	0.094				\$481,578.92
	soft costs include A/E, CA, & DPW, etc.	0.30**				\$1,681,427.68
	TOTAL:					\$7,286,186.60
*	terracotta rainscreen system, el. al = \$66/SF		107,100	\$65.00	\$6,961,500.00	
	stone rainscreen system, el. al = \$75/SF		107,100	\$75.00	\$8,032,500.00	
**	Based on total value of a larger project size.					
Some of the dollar figures used were calculated based on information obtained from the 2006 Building Construction Cost Data, published by Robert Snow Means Company, Inc. Kingston, Massachusetts. Additional figures were obtained from similar active projects with inflation and geographical percentages included and manufacturer's pricing. The final dollar amount shown is for guidance only and is a "ball park" figure. An assumption is made that all repair work will be performed under one contract and not spaced out over a period of time. The amount does not include any Architectural / Engineering fees or contingencies. Total dollar amount to be adjusted if work is to be performed during off hours or on weekends.						

*add'l
 back up to
 # 2*

Martin A. Benassi AIA		COST ESTIMATE - Appendix C				Design Phase
Architect		DPW #BI-2B-033-I				
Drainage Plane Study - 25 Sigourney Street		Date: July 21, 2006				Page 4 of 5
DIV.	PRINCIPAL TRADE ITEM AND ITEM DESCRIPTION	UNIT	QTY	UNIT PRICE	ITEM PRICE	SELECTED ITEM COST
	GENERAL					
	bonding, insurance, general administrative	unit	1	\$150,000.00	\$150,000.00	
	scaffolding, swing staging rental and equip.	mo	4	\$6,000.00	\$24,000.00	
	site foreman, supervision	mo	4	\$11,000.00	\$44,000.00	
						\$218,000.00
	OPTION D - rem/replace brick & add barrier					
	remove and replace brick veneer	sf	107,100	\$45.00	\$4,819,500.00	
	remove & replace rigid insulation	sf	107,100	\$1.25	\$133,875.00	
	install barrier on exterior of existing CMU	sf	107,100	\$3.00	\$321,300.00	
	sealant	u	1	\$8,000.00	\$8,000.00	
						\$5,282,675.00
	SUB-TOTAL					\$5,500,675.00
	city cost index	0.094				\$517,063.45
	soft costs include A/E, CA, & DPW, etc.	0.30**				\$1,805,321.54
	TOTAL:					\$7,823,059.99
	** Based on total value of a larger project size.					
<p>Some of the dollar figures used were calculated based on information obtained from the 2006 Building Construction Cost Data, published by Robert Snow Means Company, Inc. Kingston, Massachusetts. Additional figures were obtained from similar active projects with inflation and geographical percentages included and manufacturer's pricing. The final dollar amount shown is for guidance only and is a "ball park" figure. An assumption is made that all repair work will be performed under one contract and not spaced out over a period of time. The amount does not include any Architectural / Engineering fees or contingencies. Total dollar amount to be adjusted if work is to be performed during off hours or on weekends.</p>						

Back up for # 3

Martin A. Benassi AIA		COST ESTIMATE - Appendix C				Design Phase
Architect		DPW #BI-2B-033-I				
Drainage Plane Study - 25 Sigourney Street		Date: July 21, 2006				
DIV.	PRINCIPAL TRADE ITEM AND ITEM DESCRIPTION	UNIT	QTY	UNIT PRICE	ITEM PRICE	SELECTED ITEM COST
	GENERAL					
	bonding, insurance, general administrative	unit	1	\$98,000.00	\$98,000.00	
	scaffolding, swing staggng rental and equip.	mo	4	\$2,000.00	\$8,000.00	
	site foreman, supervision	mo	4	\$11,000.00	\$44,000.00	
	ADDITIONAL ITEMS - enclose terraces					\$150,000.00
	enclose terraces with greenhouse windows	sf	10,000	\$110.00	\$1,100,000.00	
	remove existing safety line tie back anchors	u	50	\$250.00	\$12,500.00	
	remove sliding doors and adjacent glazing (optional)	u	27	\$4,500.00	\$121,500.00	
	remove existing railings	lf	746	\$35.00	\$26,110.00	
	miscellaneous interior finishes and trim	u	27	\$12,000.00	\$324,000.00	
	revlse mechanical system	u	1	\$45,000.00	\$45,000.00	
	SUB-TOTAL					\$1,629,110.00
	city cost index					\$1,779,110.00
	soft costs include A/E, CA, & DPW, etc.	0.094				\$167,236.34
	TOTAL:	0.30**				\$583,903.90
	** Based on total value of a smaller project size.					\$2,530,250.24
<p>Some of the dollar figures used were calculated based on information obtained from the 2006 Building Construction Cost Data, published by Robert Snow Means Company, Inc. Kingston, Massachusetts. Additional figures were obtained from similar active projects with inflation and geographical percentages included and manufacturer's pricing. The final dollar amount shown is for guidance only and is a "ball park" figure. An assumption is made that all repair work will be performed under one contract and not spaced out over a period of time. The amount does not include any Architectural / Engineering fees or contingencies. Total dollar amount to be adjusted if work is to be performed during off hours or on weekends.</p>						

WING'S



TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634

25 Sigourney Street
Hartford, CT

* * * *

B.V.H. Integrated Services
Attn: Jeff Cichonski
50 Griffin Road South
Bloomfield, CT 06002

June 21, 2006

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

SM-1 License # 5775

File: Sigoumey Street

WING'S



TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634

June 21, 2006

B.V.H. Integrated Services
Attn: Jeff Cichonski
50 Griffin Road South
Bloomfield, CT 06002

Re: 25 Sigourney Street, Hartford, CT


Dear Jeff:

Testing for the above referenced location has been completed. Fan totals for CEF-1 and 2, as well as Ref-1, could not be obtained by Velocity Pressure Traverse, and outlet summation would require further time and investigation. Total flows for the remainder of the fans requested are as listed on the following pages.

If you have any questions regarding the information provided, or if we can be of further assistance, please do not hesitate to call.

Very truly yours,
Wing's Testing & Balancing Co., Inc.

John Flanagan
Certified TABB Technician #BB040033
CT SM-2 License 771



Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com
SM-1 License # 5775

File: Sigourney Street

EXHAUST FAN REPORT


PROJECT: 25 SIGOURNEY STREET	DATE: 6/7/06
AREA SERVED: HARTFORD, CT	TECH: J. FLANAGAN

FAN DATA						
FAN NUMBER		CEF-1	CEF-2	REF-1		
LOCATION		ROOF	ROOF	ROOF		
AREA SERVED		CAFETERIA	CAFETERIA	TOILETS		
MANUFACTURER		CENTRIMASTER	CENTRIMASTER	CENTRIMASTER		
MODEL OR SIZE		PUB256IU	PUB300IU	M#PN365N		
TOTAL CFM	DESIGN	N.L.	N.L.	15600		
	ACTUAL	(1)	(1)	(1)		
FAN RPM	DESIGN	N.L.	N.L.	N.L.		
	ACTUAL	814	739	761		
PULLEY O.D.		5 1/2" X 1"	9" X 1"	13 1/8" X 1 3/16"		
SUCTION SP.		-1.15" (3)	-1.34" (3)	-.627 (3)		

MOTOR DATA						
MANUFACTURER		MAGNETEC	MAGNETEC	CENTURY		
MODEL NUMBER		FRS182T	FRS184T	FR:S184T		
MOTOR HP	DESIGN	N.L.	N.L.	N.L.		
	ACTUAL	3	5	5		
MOTOR RPM		1740	1786 (2)	1745		
VOLTAGE/PHASE		460/3	460/3	460/3		
MOTOR AMPS	DESIGN	4.3	7.2	7.2		
	ACT. LEG 1	2.3	4.5	7.4		
	ACT. LEG 2	2.5	4.7	7.6		
	ACT. LEG 3	2.1	4.1	7.5		
SHEAVE		3 1/4" X 1 1/8"	4" X 1 1/8"	6 1/2" X 1 1/8"		
BELTS-QTY/SIZE		2/AP26	2/AP41	1/AX62		
SHEAVE POSITION						

REMARKS
<p>(1) NO SUITABLE LOCATION FOR READING.</p> <p>(2) NAMEPLATE LISTING HAS BEEN SCRATCHED OFF.</p> <p>(3) SUCTION S.P. IS MEASURED BEFORE THE MOTORIZED BACKDRAFT DAMPER.</p>

NOTE:
REFER TO NET DRAWINGS
FOR ADDITIONAL INFORMATION



STATE OF CONNECTICUT DEPARTMENT OF PUBLIC WORKS	
PROJECT NO.	10-100
DATE	10-100
SCALE	AS SHOWN
DESIGNED BY	BMH INCORPORATED SERVICES, INC. 1000 WEST 10TH AVENUE DENVER, CO 80202
CHECKED BY	ARCHITECTURAL SERVICES
APPROVED BY	ARCHITECTURAL SERVICES
DATE	10-100
PROJECT NO.	10-100
DATE	10-100
SCALE	AS SHOWN
DESIGNED BY	BMH INCORPORATED SERVICES, INC. 1000 WEST 10TH AVENUE DENVER, CO 80202
CHECKED BY	ARCHITECTURAL SERVICES
APPROVED BY	ARCHITECTURAL SERVICES
DATE	10-100

EXISTING STAIRWELL
CHASSEL

EXISTING ELEVATOR
CHASSEL

EXISTING CHASSEL
CHASSEL

EXISTING STAIRWELL
CHASSEL

EXISTING ELEVATOR
CHASSEL

EXISTING CHASSEL
CHASSEL

REPLACE EXISTING
ACTUATOR & FALL
SWITCH WITH NEW
ACTUATOR & FALL
SWITCH

SEE SCHEDULE OF MATERIALS FOR
ACTUATOR & FALL SWITCH

EXISTING STAIRWELL
CHASSEL

EXISTING ELEVATOR
CHASSEL

EXISTING CHASSEL
CHASSEL

Sizes and (A) decibels are shown in curve form on the performance charts on pages 7 through 10.




DEFINED CFM, BHP, HORSEPOWER VS. STATIC PRESSURE


MODEL NO.	FAN: MIN. MAX.		HP	0"		.125"		.250"		.375"		.500"		.750"		1.000"		1.500"		2.000"		EST. CHP WT.
	RPM	TIP SPEED		CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	CFM	BHP	
PN300F	286	2246	1/2	4480	.08	3430	.11	8020	.33	4110	.36											330
	414	3251		6460	.23	5760	.28															
PN300G	321	2921	1/2	6010	.11	4100	.19	2840	.17													397
	473	4714		7260	.34	8770	.40	8140	.46	8480	.51	4600	.53									
PN300H	399	3139	3/4	8230	.20	5500	.23	4740	.30	3680	.32											340
	650	4818		8680	.53	8060	.60	7530	.67	8880	.73	6420	.79	4710	.82							
PN300J	430	3440	1	8030	.27	8170	.32	5490	.38	4720	.42	3390	.41									343
	604	4743		9420	.70	8950	.78	8470	.85	7970	.93	7470	1.00	6800	1.10	8460	.93					
PN300K	488	3817	1 1/2	7680	.36	7000	.43	6490	.49	5750	.54	4960	.57									358
	670	5282		10450	.93	10020	1.04	9590	1.13	9150	1.21	8710	1.29	7780	1.43	6680	1.50					
PN300L	545	4280	2	8500	.51	7870	.58	7440	.65	6890	.72	6310	.77	4520	.79							361
	762	5906		11730	1.34	11380	1.44	10970	1.54	10560	1.64	10190	1.73	8890	1.90	8540	2.05	8470	2.00			
PN300M	682	5120	3	10170	.88	9730	.96	9290	1.05	8840	1.13	8380	1.21	7410	1.34	6000	1.38					368
	843	6820		13150	1.89	12810	2.00	12470	2.11	12130	2.22	11780	2.33	11100	2.53	10380	2.72	8620	2.98			
PN365G	240	2388	1/2	6290	.14	4710	.18	2590	.19													445
	361	3449		9100	.42	8000	.47	7000	.54	5890	.57	4240	.56									
PN365H	288	2733	3/4	7210	.32	5860	.26	4880	.29													448
	417	3884		10510	.65	9330	.70	8050	.77	7780	.83	6700	.88									
PN365J	295	2818	1	7440	.24	6180	.28	4760	.32													451
	445	4252		11220	.78	10320	.84	8480	.91	8030	.99	7740	1.05	6340	1.04							
PN365K	358	3373	1 1/4	8900	.40	7800	.43	6730	.51	6480	.54	3800	.52									463
	520	4968		13110	1.24	12390	1.30	11800	1.38	10900	1.47	10200	1.57	8900	1.68	8500	1.66					
PN365L	423	4042	2	10670	.67	9720	.73	8920	.80	7950	.88	6930	.91									470
	571	6468		14490	1.64	13700	1.70	13000	1.78	12320	1.88	11600	1.98	10360	2.17	8740	2.22					
PN365M	508	4884	3	12810	1.15	12010	1.22	11230	1.30	10310	1.39	8790	1.48	8100	1.57	6850	1.54					484
	666	6288		18540	2.45	18020	2.54	17310	2.62	16720	2.72	16140	2.84	13020	3.11	11850	3.28	8880	3.33			
PN365N	640	6118	5	16140	3.28	15500	3.36	14880	3.45	14270	3.55	13680	3.66	12640	3.89	11810	3.07	8090	3.08			498
	775	7405		19840	4.03	19010	4.12	18490	4.22	17980	4.33	17480	4.45	16800	4.72	15980	5.00	13550	3.45	11000	3.49	
PN490H	180	2309	3/4	11000	.23	8120	.30															717
	252	3232		15400	.61	10300	.70	11300	.80	8800	.88											
PN490J	182	2334	1	11100	.23	8280	.30															720
	278	3888		16960	.82	15020	.91	13250	1.04	11230	1.11	8740	1.10									
PN490K	226	2898	1 1/4	13800	.44	11500	.53	9130	.60	5700	.58											732
	318	4079		19400	1.22	17700	1.32	16100	1.45	14930	1.58	12800	1.66									
PN490L	230	3027	2	14400	.50	12170	.59	10000	.68	7900	.68											738
	380	4488		21350	1.62	18800	1.73	18330	1.86	16920	2.02	15460	2.15	11700	2.20							
PN490M	314	4028	3	13150	1.17	12440	1.27	11820	1.40	14240	1.53	12400	1.60									794
	408	5131		24400	2.41	23037	2.53	21720	2.67	20486	2.84	19230	3.02	16360	3.27	13140	3.27					
PN490N	338	4836	5	20620	1.46	19020	1.56	17800	1.70	16040	1.85	14300	1.96	10420	1.97							808
	475	6093		28980	4.02	27820	4.16	26700	4.31	25800	4.42	24540	4.70	22460	3.11	20240	3.43	14380	3.43			
PN490P	431	5529	7/8	26800	3.01	25000	3.14	23800	3.28	22600	3.46	21450	3.61	19100	4.00	16300	4.12					827
	543	6988		33120	5.99	32110	6.15	30110	6.32	28140	6.51	26200	6.73	23800	7.19	20830	7.67	21390	8.21	18900	8.08	
PN543J	169	2400	1	14000	.31	10620	.40	6120	.41													780
	239	3394		19800	.86	17320	.97	15020	1.11	12310	1.17	8860	1.14									
PN543K	185	2027	1 1/2	15900	.40	12200	.50	8890	.53													772
	273	3877		22600	1.28	20400	1.39	18400	1.53	16300	1.70	13800	1.74									
PN543L	200	2840	2	18500	.51	13600	.61	10800	.69													779
	296	4203		24500	1.62	22480	1.75	20570	1.91	18730	2.09	16700	2.21	11200	2.17							
PN543M	243	3461	3	20120	.90	17700	1.01	15020	1.16	12830	1.23	9380	1.21									804
	341	4843		28230	2.47	26460	2.62	24770	2.79	23180	3.09	21340	3.19	17800	3.39	12800	3.32					
PN543N	305	4331	6	25250	1.77	23280	1.90	21420	2.07	19890	2.23	17780	2.39	12720	2.40							839
	400	5881		33110	3.99	31600	4.13	30130	4.33	28700	4.55	27320	4.79	24570	5.24	21880	5.46					
PN543P	360	4871	7/8	26980	2.67	27250	2.82	26600	2.99	24100	3.20	22450	3.41	18940	3.66	14340	3.62					850
	460	6533		38077	6.05	36780	6.21	35470	6.44	34220	6.68	32870	6.93	30380	7.17	28180	7.98	22200	8.29			
PN543R	397	5638	10	32900	3.90	31300	4.06	29900	4.24	28400	4.46	27000	4.68	24200	5.14	21000	5.34					861
	508	7172		41800	8.00	40800	8.20	39400	8.42	38200	8.65	37100	8.91	34800	9.50	32780	10.10	28000	10.91	21900	10.88	

REF-1
INTERPOLATION:
16,490 CFM

PERFORMANCE CHART PUB 245



PERFORMANCE CHART PUB 300



Performance shown is for units without duct. DHP for belt driven units does not include drive losses.

BELT DRIVEN

CERTIFIED CFM, BHP AND SOUND VS. STATIC PRESSURE TO 250'

MODEL NO.	FAN RPM	MIN. TYP. MAX. SPEED	HP	1.000"		1.250"		1.500"		1.750"		2.000"		2.250"		2.500"		BPT SHIP WT.	
				CFM	*BHP	CFM	*BHP	CFM	*BHP	CFM	*BHP	CFM	*BHP	CFM	*BHP	CFM	*BHP		
PUB135F	1032 1546	3647 5471	1/4	755	.01														
PUB135G	1848 1848	4390 6524	1/4	1420	.20	1140	.54	785	.48									148	
PUB145F	778 1870	2983 4849	1/4															150	
PUB145F	918 1870	3465 5829	1/4	560	.27													150	
PUB145G	1148 1890	4362 7415	1/4	1845	.88	1170	.55	898	.48									160	
PUB145H	1300 1818	4936 7283	3/4	2070	.84	1785	.80	1470	.82	1035	.70	895	.84					160	
PUB163E	741 1110	3102 4722	1/4															169	
PUB163F	835 1228	3582 5228	1/4	820	.33													168	
PUB163G	834 1228	3870 6082	1/4	1720	.98	1190	.58											186	
PUB163H	1088 1577	4540 8883	3/4	2870	.78	1855	.77	1960	.71									188	
PUB200E	800 820	3776 4891	1/4															188	
PUB200F	532 826	4308 6744	1/4															255	
PUB200G	710 1048	3710 5493	1/4	2000	.57	1610	.59											255	
PUB200H	807 1105	4288 6125	1/4	2880	.79	2205	.75											268	
PUB200J	804 1510	4738 8823	1	3330	1.10	3015	1.11	2625	1.11	1809	1.02							268	
PUB200K	1070 1478	5006 7792	1 1/2	4144 3985	.87			3770	1.07	3600	1.58	3180	1.67	2770	1.56	2040	1.54	209	
PUB200L	1184 1638	6003 8866	1	4756 4880	.86	2315 2.04	4390	2.02	1290	.88	4185	2.12	3860	2.14	3888	2.12	2040	1.54	287
PUB245F	481 890	2247 4205	1/4																
PUB245G	523 788	3885 4832	1/4																277
PUB245H	610 894	4918 5670	1/4	1115	.83														277
PUB245J	845 948	4137 6087	1	3695	1.02	3470	1.02												285
PUB245K	738 1030	4724 6880	1 1/2	4720	1.52	4235	1.54	3800	1.52	3145	1.51							289	
PUB245L	852 1180	5528 7808	2	2880 3025	.77	1.85	5088	2.00	4750	2.02	4080	2.02	3780	2.00	1875	1.58			287
PUB245M	1091 1390	6988 8515	3	4788 5695	1.84	4375	1.58	3900	1.45	3225	1.53							287	
PUB300H	385 683	3102 4857	1/4																
PUB300J	481 663	3778 5129	1	2580	.88														412
PUB300K	553 751	4343 6808	1 1/2	5830	1.82	4930	1.60												413
PUB300L	603 910	4786 6981	2	5688	1.80	4888	2.02	4140	1.88										411
PUB300M	663 887	5807 7280	3	3720 4180	1.08	3.08	7820	3.07	6885	3.04	6188	3.01	4178	2.89					425
PUB300N	820 1109	6440 8939	5	8880	2.18	10206	4.88	5650	2.09	4880	2.06	4485	2.06	4188	2.89				482
PUB365H	279 426	2656 4071	1/4																
PUB365J	413 482	2991 4482	1																479
PUB365K	475 592	3583 5084	1 1/2																518
PUB365L	385 583	2778 3657	1/4																519
PUB365M	404 477	4721 6489	1	7980	2.22														517
PUB365N	800 788	6307 7886	1	10100	3.34	8980	3.31	6780	3.08										528
PUB490K	848 325	2800 6188	1 1/2																848
PUB490L	288 303	3428 4857	1/4																561
PUB490M	380 410	3823 5288	1																768
PUB490N	410 505	5200 8478	1	7485	2.64	8448	2.41	10702	5.81	14519	6.88	10940	4.78						808

✓ CEF-2


INTERPOLATED 6550 CFM

WING'S




TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634



25 Sigourney St.
ATC Upgrades



* * * *

REVIEWED FOR RECORDS ONLY
BVH INTEGRATED SERVICES, INC.

By PB Date 2-4-05

Invensys
Attn.: Ron Duplin
29 Kripes Road
PO Box 575
East Granby, CT 06026

January 17, 2005

- Reviewed For Record
- 1) were The Defective Devices Noted Repaired
 - 2) Reuse and ReSubmi as Noted
 - 3) Reference Tube must Be Repair For system TO operate Properly

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

File: 25 sigourney st ATC Upgrades.

SM-1 License # 5775

WING'S



TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634

July 2004
25 Sigourney Street
ATC Upgrades
Pressure Testing

Floors	Test 1	Final
	Actual/Invensys	Actual/Invensys
6TH FLOOR		
SPACE	.20/.10	
SA SPN	1.13/1.15	1.13/1.14
SA SPS	1.25/1.26	1.25/1.26
MIN. O.A. N.	.033/.03	.030/.03
MIN. O.A. S.	.038/.04	.030/.03
5TH FL. MEZZ.		
MESS. SPACE	.08/.07	.08/.07
LOBBY SPACE	.08/.08	.08/.08
SA SPN	.77/.78	.77/.78
SA SPS	1.06/1.07	1.06/1.07
MIN. O.A. N.	.015/.02	.019/.02
MIN O.A. S.	.026/.03	.029/.03
10TH FLOOR		
SPACE	.18/.10	
SA SPN	1.31/1.34	1.30/1.30
SA SPS	1.12/1.15	1.14/1.14
MIN. O.A.N.	.028/.03	.031/.03
MIN. O.A.S.	.030/.03	.030/.03
9TH FLOOR		
SPACE	.23/.10	
SA SPN	1.28/1.31	1.28/1.28
SA SPS	1.12/1.15	1.14/1.14
MIN. O.A.N.	.031/.03	.031/.03
MIN. O.A.S.	.03/.03	.03/.03
8TH FLOOR		
SPACE	.29/.10	
S.A. SPN	1.095/1.12	1.11/1.11
SA SPS	1.12/1.14	1.15/1.15
MIN. O.A.N.	.030/.03	.030/.03
MIN. O.A.S.	.030/.03	.030/.03

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

File: 25 SIGOURNEY ST.

SM-1 License # 5775

WING'S



TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634

July 2004
25 Sigourney Street
ATC Upgrades
Pressure Testing

Floors	Test 1	Final
	Actual/Invensys	Actual/Invensys
7TH FLOOR		
SPACE	.31/.10	
SA SPN	1.18/1.22	1.21/1.21
SA SPS	1.12/1.14	1.14/1.14
MIN. O.A. N.	.028/.03	.03/.03
MIN. O.A. S.	.024/.03	.031/.03
15TH FL.		
SPACE	.04/.04	.04/.04
SA SPN	1.04/1.06	1.04/1.06
SA SPS	.81/.83	.81/.83
MIN. O.A. N.	.038/.04	.04/.04
MIN O.A. S.	.05/.07	.029/.03
14TH FLOOR		
SPACE	.04/.04	.04/.04
SA SPN	1.12/1.14	1.12/1.14
SA SPS	1.20/1.18	1.20/1.18
MIN. O.A.N.	.031/.03	.030/.03
MIN. O.A.S.	.03/.03	.03/.03
12TH FLOOR		
SPACE	.17/.10	OVER RANGE (VERIFY)
SA SPN	1.13/1.15	1.13/1.15
SA SPS	1.13/1.19	1.13/1.13
MIN. O.A.N.	.03/.03	.03/.03
MIN. O.A.S.	.03/.03	.021/.02
11TH FLOOR		
SPACE	.22/.10	OVER RANGE (VERIFY)
S.A. SPN	1.23/1.25	1.23/1.25
SA SPS	1.13/1.15	1.13/1.15
MIN. O.A.N.	.03/.03	.03/.03
MIN. O.A.S.	.033/.03	.03/.03

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

File: 25 SIGOURNEY ST

SM-1 License # 5775

WING'S



TESTING & BALANCING CO., INC.

94 No. Branford Rd., Branford, CT 06405
203-481-4988 Fax 203-488-5634

July 2004
25 Sigourney Street
ATC Upgrades
Pressure Testing

Floors	Test 1	Final
	Actual/Invensys	Actual/Invensys
19TH FLOOR (1)		
SPACE/ATMOS.	+17/+10	OUT OF RANGE
SA SPN	1.17/1.18	1.17/1.18
SA SPS	1.13/1.15	1.13/1.14
MIN. O.A. N.	.023/.02	.02/.02
MIN. O.A. S.	.009/.01	.01/.01
18TH FL.		
SPACE	+29/+10	OUT OF RANGE
SA SPN	1.16/1.19	1.21/1.20
SA SPS	1.12/1.15	1.13/1.13
MIN. O.A. N.	.05/.05	.05/.05
MIN O.A. S.	.042/.04	.04/.04
17TH FLOOR (2)		
SPACE	+19/+10	OUT OF RANGE
SA SPN	1.24/1.29	1.24/1.26
SA SPS	1.13/1.13	1.13/1.13
MIN. O.A.N.	.029/.03	.029/.03
MIN. O.A.S.	.04/.04	.04/.04
16TH FLOOR		
SPACE	.02/.02	.02/.02
SA SPN	1.29/1.30	1.29/1.30
SA SPS	1.17/1.17	1.17/1.17
MIN. O.A.N.	.03/.03	.03/.03
MIN. O.A.S.	.02/.02	.03/.03

(1) ACTUAL SPACE PRESSURE = +.05.

(2) ACTUAL SPACE PRESSURE = +.065

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

File: 25 SIGOURNEY ST

SM-1 License # 5775



July 2004
 25 Sigourney Street
 ATC Upgrades
 Pressure Testing

O.A. SF-1 NORTH	TEST 1	FINAL
	ACTUAL/INVENSYS	ACTUAL/INVENSYS
6TH FLOOR	.17/.17	.17/.17
8TH FLOOR	.17/.17	.17/.17
16TH FLOOR	.17/.15	.18/.18
AVG.	.17/.16	.17/.17 SPT = .17"

O.A. SF-2 SOUTH	TEST 1	FINAL
	ACTUAL/INVENSYS	ACTUAL/INVENSYS
6TH FLOOR	.21/.21	.21/.21
8TH FLOOR	.20/.20	.20/.20
16TH FLOOR	.21/.21	.21/.21
AVG.	.21/.21	.21/.21 SPT = .21"

Visit us on the Internet: www.wingstesting.com or e-mail us: wings@wingstesting.com

File: 25 SIGOURNEY ST

SM-1 License # 5775

BVH
NOT W/IN SPECIFIED TOLERANCE

AIR DEVICE/BOX REPORT

PROJECT: 25 SIGOURNEY ST. ATC UPGRADES DATE: 7-15-04
 SYSTEM/AREA SERV: OASF/MEZZ. 20TH FL. TECH: J.F.

LOCATION	NO.	SIZE	FREE AREA	DESIGN CFM		TEST I	FINAL CFM		PRESS. DIFF.		NOTES
				MIN	MAX		MIN	MAX	MIN	MAX	
OASF-1 NO.											(1,2)
FLR. # 19		28X16	3.11	2200	3600	1956	1956	2660	.02	.037	(3)
18		28X16		2000	3275	2985	1969	2612	.025	.044	(3)
17		28X16		2000	3275	1978	1978	2545	.029	.048	(3)
16		28X16		2200	3600	2264	2264	2647	.03	.041	(3)
15		28X16		2200	3600	2183	2183	2183	.04	.04	(3)
14		28X16		2200	3600	2333	2333	2520	.03	.035	(3)
12		28X16		2200	3600	2027	2027	2510	.03	.046	(3)
11		28X16		2200	3600	2403	2403	2740	.03	.039	(3)
10		28X16		2200	3600	2224	2224	2526	.031	.040	(3)
9		28X16		2200	3600	2158	2158	2451	.031	.040	(3)
8		28X16		2200	3600	2074	2074	2731	.03	.052	(3)
7		28X16		2200	3600	2127	2127	2932	.03	.057	(3)
6		28X16		2200	3600	2258	2258	2856	.03	.048	(3)
MEZZ. 2N		28X16		1600	2625	1696	1696	1725	.029	.03	(3)
AHU-1		48X20		0	0	0	0	0			(4)

IS THIS OCCUPIED SPACE?
BVH

REMARKS

- (1) OASF-1 OPERATING @ 54 HZ 27.2 AMPS UNDER MIN. CONDITION.
- (2) OASF-2 OPERATING @ 59.6 HZ 31.7 AMPS UNDER MAX. CONDITION.
- (3) DAMPER IS 100% OPEN UNDER MAX. CONDITION.
- (4) DAMPER IS CLOSED 100%.

VELOCITY PRESSURE READINGS										
PROJECT:		25 SIGOURNEY ST., ATC UPGRADES					DATE: 7-6-04			
LOCATION:		AIR HANDLER TOTALS					TECH: S.W. & J.F.			
TRAVERSE LOCATIONS	DUCT SIZE	AREA SQ. FT.	DESIGN		CENTERLINE STATIC PRES.	FINAL		NOTES		
			FPM	CFM		FPM	CFM			
MEZZ. NORTH	82X22	12.52	839	10500	W/GRID	731	9152			
MEZZ SOUTH	104X28.75	19.11	743	14200	W/GRID	752	14370			
6 NORTH	104X28.75	19.11	759	14500	W/GRID	804	15364			
6 SOUTH	104X28.75	19.11	759	14500	W/GRID	860	16435			
7 NORTH	104X28.75	19.11	759	14500	W/GRID	886	16931			
7 SOUTH	104X28.75	19.11	759	14500	W/GRID	859	16415			
8 NORTH	104X28.75	19.11	759	14500	W/GRID	852	16282			
8 SOUTH	104X28.75	19.11	759	14500	W/GRID	877	16759			
9 NORTH	104X28.75	19.11	759	14500	W/GRID	770	14715			
9 SOUTH	104X28.75	19.11	759	14500	W/GRID	767	14657			
10 NORTH	104X28.75	19.11	759	14500	W/GRID	874	16702			
10 SOUTH	104X28.75	19.11	759	14500	W/GRID	917	17524			
11 NORTH	104X28.75	19.11	759	14500	W/GRID	958	18307			
11 SOUTH	104X28.75	19.11	759	14500	W/GRID	870	16626			
12 NORTH	104X28.75	19.11	759	14500	W/GRID	874	16702			
12 SOUTH	104X28.75	19.11	759	14500	W/GRID	855	16339			
14 NORTH	104X28.75	19.11	759	14500	W/GRID	883	16874			
14 SOUTH	104X28.75	19.11	759	14500	W/GRID	948	18116			
15 NORTH	104X28.75	19.11	759	14500	W/GRID	814	15555			
15 SOUTH	104X28.75	19.11	759	14500	W/GRID	848	16205			
16 NORTH	104X28.75	19.11	759	14500	W/GRID	721	13778			
16 SOUTH	104X28.75	19.11	759	14500	W/GRID	743	14199			
17 NORTH	104X28.75	19.11	706	13500	W/GRID	836	15976			
17 SOUTH	104X28.75	19.11	706	13500	W/GRID	845	16148			
18 NORTH	104X28.75	19.11	706	13500	W/GRID	838	16014			
REMARKS										

