

**Interim Technical
Memorandum #1**

(Existing and Future Deficiencies)

Seymour

Beacon Falls

Naugatuck

Waterbury

prepared for:



prepared by:

Vanasse Hangen Brustlin, Inc. 

August 2009

Route 8

Interchanges 22-30 Deficiencies/Needs Study




Table of Contents

1. Introduction	1-1
1.1 Study Goals and Objectives	1-1
1.2 Study Area	1-2
1.3 Study Process	1-3
1.4 Public Participation	1-3
1.5 Study Team	1-4
2. Existing Transportation Conditions	2-1
2.1 Study Area Demographics	2-1
2.2 Existing Traffic Demand	2-2
2.2.1 Daily Volumes	2-2
2.2.2 Peak Hour Volumes	2-3
2.2.3 Surface Street Traffic Volumes	2-4
2.2.4 Trucks	2-5
2.2.5 Mainline Speeds	2-6
2.3 Geometrics	2-7
2.3.1 Methodology/Review of Geometrics	2-7
2.3.2 Main Line Geometry Review	2-9
2.3.3 Interchange Spacing	2-11
2.4 Structural Conditions Review	2-14
2.4.1 Operational Conditions	2-14
2.4.2 Physical Conditions	2-17
2.5 Existing Traffic Operations	2-18
2.5.1 Methodology/Criteria	2-19
2.5.2 Mainline Operations	2-19
2.5.3 Ramp Operations	2-22
2.5.4 Weaves	2-25
2.5.5 Intersections	2-27
2.6 Safety Analysis	2-33
2.6.1 Methodology	2-33
2.6.2 Quantitative Data	2-33
2.6.3 Review of Route 8 Accident Locations	2-36
2.6.4 Local Intersections	2-38
2.7 Multi- Modal Transportation Services	2-40
2.7.1 Metro North Railroad	2-40
2.7.2 Park and Ride Facilities	2-41
2.7.3 Transit	2-42
2.7.4 Bicycle and Pedestrian Access	2-43

3. Existing Environmental Conditions	3-1
3.1 Community Resources.....	3-2
3.1.1 Sensitive Noise Receptors.....	3-2
3.1.2 Land Use, Community Planning and Municipal Facilities.....	3-5
3.1.3 Local, Regional and State Land Use Plans.....	3-9
3.2 Natural Resources.....	3-13
3.2.1 Surface Water Resources.....	3-14
3.2.2 Wetlands.....	3-16
3.2.3 Floodplains and Stream Channel Encroachment Lines.....	3-18
3.2.4 Groundwater Resources.....	3-20
3.2.5 Endangered Species.....	3-21
3.2.6 Farmland Soils.....	3-23
3.3 Cultural and Recreational Resources.....	3-24
3.3.1 Cultural Resources.....	3-24
3.3.2 Section 4 (f) and 6 (f) Lands.....	3-29
3.4 Other Environmental Factors.....	3-31
3.4.1 Hazardous Materials.....	3-31
3.4.2 Environmental Justice.....	3-33
4. Future Transportation Conditions	4-1
4.1 Forecasting Future Traffic Conditions – 2008 to 2030.....	4-1
4.1.1 Study Area Land Use Update.....	4-2
4.2 Future Traffic Demand – Year 2030.....	4-3
4.2.1 2030 Daily Volumes.....	4-4
4.2.2 2030 Peak Hour Volumes.....	4-4
4.3 Future Traffic Operations – Year 2030.....	4-6
4.3.1 Mainline Operations.....	4-6
4.3.2 Ramp Operations.....	4-8
4.3.3 Weaves.....	4-10
4.3.4 Intersections.....	4-11
4.3.5 Comparison of Existing and Future Conditions.....	4-16
5. Deficiencies and Needs Summary	5-1
5.1 Future Conditions – Year 2030.....	5-1
5.1.1 Geometric Assessment.....	5-1
5.1.2 Structural Evaluation.....	5-2
5.1.3 Traffic Operations.....	5-2
5.1.4 Safety.....	5-3
5.2 Future Conditions – Year 2030.....	5-4
5.2.1 Traffic Demand.....	5-4
5.2.2 Traffic Operations.....	5-4

Appendix

- A-1 Surface Street Intersections
- A-2 Existing and Future Transportation Conditions Graphics
- A-3 Summary of Accident Analysis

- B-1 Environmental Constraints Mapping
- B-2 Environmental Conditions - Coordination Letters

List of Tables

Table No.	Description	Page
2-1	Study Area Demographics/Trip Generation.....	2-1
2-2	Route 8 Average Annual Daily Traffic Volumes (AADT)	2-2
2-3	Route 8 Peak Hour Mainline Volumes - 2008 Existing Conditions.....	2-4
2-4	Vehicle Classification Study Results	2-5
2-5	Route 8 - Mainline Design Criteria.....	2-8
2-6	Route 8 - Mainline Geometric Compliance - Northbound.....	2-9
2-7	Route 8 - Mainline Geometric Compliance - Southbound	2-10
2-8	Route 8 - On-Ramp Locations - Geometric Assessment	2-12
2-9	Route 8 - Off-Ramp Locations - Geometric Assessment	2-13
2-10	Route 8 - Bridge Structure Summary	2-15
2-11	Route 8 - Bridge Operational Conditions Summary	2-16
2-12	Route 8 - Bridge Physical Conditions Summary	2-17
2-13	Summary of Freeway Segment Analysis - 2008 Existing Conditions.....	2-21
2-14	Ramp Level-of-Service Analysis Summary - 2008 Existing Conditions	2-24
2-15	Weaving Sections Level-of-Service Analysis Summary - 2008 Existing Conditions	2-27
2-16	Signalized Intersection Level-of-Service Summary - 2008 Existing Conditions	2-29
2-17	Unsignalized Intersection Level-of-Service Summary - 2008 Existing Conditions	2-30
2-18	Total Study Area Accidents by Year.....	2-34
2-19	Vehicle Classifications for Accidents in Study Area	2-34
2-20	Comparison of Accident Road Surface Conditions	2-35
2-21	Contributing Factors for Accidents in Study Area.....	2-35
2-22	Accident Summary for Local Intersections (2005-2007)	2-39
2-23	Waterbury Branch Parking	2-41
2-24	Route 8 Corridor Park and Ride Lots	2-42
3-1	Noise Sensitive Receptors within the Route 8 Study Area.....	3-3
3-2	Public Safety Facilities and Community Institutions located within the Study Area.....	3-9
3-3	Surface Water Quality Classifications	3-15
3-4	Stream Crossing within the Route 8 Study Area	3-16
3-5	Wetlands within the Route 8 Study Area.....	3-18
3-6	CTDEP Groundwater Quality Classifications in Study Area.....	3-21
3-7	Known Historic Resources within the Route 8 Study Area.....	3-25
3-8	Potential Section 4(f) Resources (Non – Historic) within the Route 8 Study Area	3-30
3-9	Hazardous Material Sites within the Route 8 Study Area.....	3-33

List of Tables(Cont'd)

3-10 Demographic Data for the Study Area Compared to State of Conencticut 3-35

3-11 Environmental Justice Data for the Route Study Area –Minority and Below - Poverty Populations..... 3-35

4-1 Route 8 Mainline Average Daily Traffic Volumes (ADT) Comparison 2008 to 2030 4-4

4-2 Route 8 Mainline Peak Hour Volume Comparison 2008 to 2030 4-5

4-3 Route 8 Peak Hour Volumes – Mainline 2030 Future Conditions 4-6

4-4 Summary of Freeway Segment Analysis 2030 Future Conditions 4-7

4-5 Ramp Level-of-Service Analysis Summary 2030 Future Conditions..... 4-9

4-6 Weaving Sections Level-of-Service Analysis Summary 2030 Future Conditions..... 4-10

4-7 Signalized Intersection Level-of-Service Summary 2030 Future Conditions..... 4-12

4-8 Unsignalized Intersection Level of-Service Summary 2030 Future Conditions..... 4-13

4-9 Comparison of Existing and Future Study Area Traffic Conditions 2008 to 2030 4-16

5-1 Comparative Levels of Service for Freeway Segments (Existing vs. 2030 Conditions) 5-5

List of Figures

Appendix A-2

Figure No.	Description
1-1	Study Area Map
1-2	Study Process
2-1	Corridor Geometric and Safety Review
2-2	Mainline/Ramp/Weave Capacity Analysis—Existing Conditions AM Peak Hour
2-3	Mainline/Ramp/Weave Capacity Analysis—Existing Conditions PM Peak Hour
2-4	Signalized Intersection Capacity Analysis—Existing Conditions AM Peak Hour
2-5	Signalized Intersection Capacity Analysis—Existing Conditions PM Peak Hour
4-1	Mainline/Ramp/Weave Capacity Analysis—2030 No-Build AM Peak Hour
4-2	Mainline/Ramp/Weave Capacity Analysis—2030 No-Build PM Peak Hour
4-3	Signalized Intersection Capacity Analysis—2030 No-Build AM Peak Hour
4-4	Signalized Intersection Capacity Analysis—2030 No-Build PM Peak Hour

Appendix B-1

Figure No.	Description
3-1	Land Use, Noise Receptors, and Potential Environmental Justice Populations
3-2	Community Facilities
3-3	Wetlands and Water Resources
3-4	Flood Plains, Stream Channel Encroachment Lines, Natural Diversity Database Records
3-5	Hazardous Materials, Historic Resources, & 4(f) Resources