



STATE OF CONNECTICUT
CONNECTICUT SITING COUNCIL

Ten Franklin Square, New Britain, CT 06051

Phone: (860) 827-2935 Fax: (860) 827-2950

E-Mail: siting.council@ct.gov

www.ct.gov/csc

March 18, 2009

Christopher B. Fisher, Esq.
Cuddy & Feder, LLP
445 Hamilton Avenue, 14th Floor
White Plains, New York 10601

RE: **DOCKET NO. 373** - New Cingular Wireless PCS, LLC (AT&T) application for a Certificate of Environmental Compatibility and Public Need for the construction, maintenance and operation of a telecommunications facility located at the St. Matthew Lutheran Church, 224 Lovely Street, Avon, Connecticut.

Dear Attorney Fisher:

The Connecticut Siting Council (Council) has revised its Set Two pre-hearing interrogatory submittal to AT&T, dated March 12, 2009. The revision (attached) includes two additional questions. The Council requests your responses to the enclosed questions no later than March 24, 2009. To help expedite the Council's review, please file individual responses as soon as they are available.

Yours very truly,



S. Derek Phelps
Executive Director

c: Council Members
Parties and Intervenors
Michele Briggs, AT&T



STATE OF CONNECTICUT
CONNECTICUT SITING COUNCIL

Ten Franklin Square, New Britain, CT 06051

Phone: (860) 827-2935 Fax: (860) 827-2950

E-Mail: siting.council@ct.gov

www.ct.gov/csc

**Docket 373: New Cingular Wireless PCS LLC
Avon, Connecticut
Pre-Hearing Interrogatories, Set Two (Revised)**

1. Provide a diagram that depicts the site property in its entirety.
2. Is AT&T amenable to installing a monopole with a flush-mounted antenna design? Describe how a flush mount antenna design would affect coverage, future equipment needs, and potential tower sharing. Provide coverage plots if necessary.
3. Is the property owner amenable to installing the tower in other locations on the property? If so, identify these locations.
4. Are there other towers or tall structures in the area (2 mile radius) that do not support AT&T's equipment? If so, please identify the structure, height of structure, address and structure location on a map.
5. What is the height of the existing church steeple? Was the existing steeple or an enlarged steeple considered for telecommunications use?
6. Provide a Natural Diversity Database map for the site area.
7. Provide the credentials of the professional that determined suitable habitat for the eastern box turtle is not present at the tower site.